Date: Friday, 29/08/2008 1:34:25 PM *User: Julie Lecocq **Process Sheet** : FLOAT SKIDTUBE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 41690 : 10366 **Estimate Number** : D412742013 **Part Number** P.O. Number : N/A : 29/08/2008 S.O. No. : **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. ; D : 29/08/2008 : SKIDTUBES Type **Drawing Revision** First Issue : 41689 Material **Previous Run** Each : 10/09/2008 Qty: 1 Um: **Due Date** Written By Checked & Approved By KJ/JLM Comment As per DSI9336 JLM Est Rev:B 06-06-08 Est RevC 07-12-03 ECN 1072 DD verified by:JLM **Additional Product** Job Number: **Machine Or Operation:** Description: Seq. #: DOCUMENT CONTROL 1.0 DC JUD 08.9,11 Comment: DOCUMENT CONTROL CH4005 Photocopy bluefile and create labels per PPP D412-742-013 — CHG004 FLOAT SKID ASSEMBLY 41690A 2.0 Comment: Sub-Component FLOAT SKID ASSEMBLY 1 x D412-742-043 PACKAGING 1 PACKAGING RESOURCE #1 3.0 Comment: PACKAGING RESOURCE #1 Pick Packing Kit 4.0 D2571 Saddle, Fwd Out 205 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qtv Part Number** Description Batch D2571 Saddle Fwd Outside 58/09/26 (FI Saddle, Fwd In 205 5.0 D2572 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch 1 D2572 Saddle Fwd Inside

Dart Aerospace Ltd

	-									
W/O:			WO	RK ORDER CHANG	ES	5.4. Life				
DATE	STEP	PR(PROCEDURE CHANGE By Date			Date	Date Qty Approval Chief Eng / Prod Mgr		Approval QC Inspector	
***************************************			- 11							
							į			
							;			
Part No:		PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQ	A:	Date: _		
Resolution:			Disposition	n:	_ QA: N/C CI	osed:	ed: Date:			
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR	1)				
DATE	STEP Description of NC		Corrective Action Section B			Verific	cation	Approval	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector	

		·								

Date: Friday, 29/08/2008 1:34:25 PM User: Julie Lecocq **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41690 * Job Number: Seq. #: Description: Machine Or Operation: Saddle, Aft Out 205 D2573 6.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qtv Part Number** Description Batch Saddle Aft Outside 1 D2573 D2574 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch (K) 1 D2574 Saddle Aft Outside D2876 8.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2876 Saddle Spacer 9.0 D2877 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2877 Saddle Spacer D34031 10.0 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description B39984 # 16 D3403-1 Bushing_ 11.0 D2747 Set Screw Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total: **Qty Part Number** Description 4 D2747 Bolt

Dart Aerospace Ltd

Duit Açı	ospace	Liu								
W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	PROCEDURE CHANGE			Da	ıte	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•			ţ					
							· · · · · · · · · · · · · · · · · · ·			
Part No:I		PAR #:	Fault Cat	egory:	_ NCR: Ye	CR: Yes No DQA: Date:				
	Resolution:			on:	_ QA: N/C	Closed	d:		Date: _	
NCR:		\	WORK ORE	DER NON-CONFORMA	ANCE (N	CR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B Sig	n &	/erific Section		Approval Chief Eng	Approval QC Inspector
	i.									

Friday, 29/08/2008 1:34:25 PM Date: Julie Lecocq User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41690 Job Number: Description: Seq. #: **Machine Or Operation:** D35331 Set Screw 12.0 Total: 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Set Screw (DOQ AN4C6A 13.0 Comment: Qty.: 16.0000 Each(s) 16.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description 16 AN4C6A Bolt AN4C52A 14.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 8 AN4C52A Bolt AN6C12A 15.0 Comment: Qty.: 8.0000 Each(s) 8.0000 Each(s)/Unit Pick: **Qty Part Number** Description 8 AN6C12A Bolt D36723 16.0 32.0000 Each(s) Comment: Qty.: Total: PHENOLIC WASHER AN960C416L 17.0 Total: 32.0000 Each(s) Comment: Qty.: 32.0000 Each(s)/Unit M108672x16 **WASHER** D36729 Phenolic Washer 18.0 Comment: Qty.: Total: 8.0000 Each(s) 8.0000 Each(s)/Unit PHENOLIC WASHER

Page 3

Form: rprocess

Dart Ae	rospace	Ltd
---------	---------	-----

									
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<u>.</u>								
									·
Part No:		PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQ	A :	Date:	
	Re	solution:	Disposition):	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORM	ANCE (NCF	₹)			
DATE	STEP	Description of NC			ion B		cation		Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
								:	
								1	

Date: Friday, 29/08/2008 1:34:25 PM User: Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41690 Job Number: Seq. #: Description: **Machine Or Operation:** WASHER AN960C616L 19.0 Comment: Qty.: Total: 8.0000 Each(s) 8.0000 Each(s)/Unit M10867 **WASHER** Phenolic Washer 20.0 D367211 Total: 16.0000 Each(s) Comment: Qty.: 16.0000 Each(s)/Unit PHENOLIC WASHER 21.0 MS210434 24.0000 Each(s) Comment: Qty.: 24.0000 Each(s)/Unit Total: Nut AN4C7A 22.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Bolt M108119 Batch: D34033 Bushing 23.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: B40528 **Qty Part Number** Description 8 D3403-3 Bushing D3405041 24.0 Lug Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description **Qty Part Number** Batch 1 D3405-041 GHW Lug 25.0 D3405043 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 08/09/26 Q 1 D3405-043 **GHW Lug**

Dart	Aeros	pace	Ltd
------	--------------	------	-----

- 4	. Johang -									
W/O:			WO	RK ORDER CHANC	GES					
DATE	STEP	PRO	OCEDURE CHAN	IGE	By Date Q			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•					ļ		
										<u> </u>
Part No		PAR #:	Fault Categ	ory:	NCR: \	/es No DQA: Date:				
	Res	solution:	Disposition	:	QA: N/	C Clos	sed:		Date: _	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC			Section B On Sign &			cation	Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Sect	ion C	Chief Eng	QC Inspector
							1		F 1	
			1 1.				1		1	1

Friday, 29/08/2008 1:34:25 PM Date: User: 🔍 Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41690 Job Number: Description: Seq. #: **Machine Or Operation:** BOLT AN4C46A 26.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Description **Qty Part Number** 4 AN4C46A Bolt MS210434 27.0 29.0000 Each(s)/Unit Total: 29.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description Batch M109148 29 MS21043-4Nut____ D3407041 28.0 Tow Ring Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch D3407-041 **TOW RING** 1 D34173 29.0 Washer Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Description **Qty Part Number** D3417-3 WASHER 2 30.0 D34561 Washer Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 10285 WASHER D3456-1 31.0 AN3C37A Comment: Qty.: 1.0000 EACH(s) 1.0000 EACH(s)/Unit Total: M109169 **BOLT**

Dart Aerospa	ce Ltd
--------------	--------

Dail Mei	Uspace	Liu							
W/O:			WO	RK ORDER CHANGE	ES				
DATE	STEP	PRO	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							!		
						A16-			
							777		
Dowt No.	_	DAD #-	Foult Cate		NCB: Voc	No. DO	۸.	Data	
Part No: PAR #: Resolution:									
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCF	₹)			.,
		Description of NC		Corrective Action Section		Verifi	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	k Sect	ion C	Chief Eng	QC Inspector
			- 9						
								1	
		· · · · · · · · · · · · · · · · · · ·							

Friday, 29/08/2008 1:34:25 PM Date: User: 🗼 🕖 Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 41690 Job Number: Description: Seq. #: **Machine Or Operation:** BOLT AN3C40A 32.0 Comment: Qty.: Total: 1.0000 Each(s) 1.0000 Each(s)/Unit 106169 **BOLT** 33.0 AN3C41A BOLT 1.0000 Each(s) Comment: Qty.: Total: 1.0000 Each(s)/Unit **BOLT** AN3C42A BOLT 34.0 Total: 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit **BOLT** BOLT AN3C43A 35.0 Comment: Qty.: Total: 4.0000 Each(s) 4.0000 Each(s)/Unit **BOLT** 36.0 AN3C46A **BOLT** Comment: Qty.: 5.0000 Each(s) 5.0000 Each(s)/Unit_ Total: W 106169 **BOLT** AN960C10L 37.0 washer ○ Comment: Qty.: Total: 26.0000 Each(s) 26.0000 Each(s)/Unit M109282 washer 38.0 MS210433 Total: 13.0000 Each(s) Comment: Qty.: 13.0000 Each(s)/Unit 1691U7 Nut **INSPECT 100% KITS FOR COMPLETENESS** QC4 39.0 Comment: INSPECT 100% KITS FOR COMPLETENESS

Dart Aerospace	Ltd
----------------	-----

D u. () (0.											
W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRC	OCEDURE CH	ANGE	By Date			Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								-			
		·	***************************************								
Part No:											
Resolution:			Dispositi	on:	_ QA: N/C C	losed:		Date: _			
NCR:			WORK ORE	DER NON-CONFORMA	ANCE (NC	R)					
DATE	OTED	Description of NC			ion B	Verifi	cation	Approval	Approval		
DAIE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector		
									4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		
		<i>.</i>						<u> </u>			
							•				

Date:

Friday, 29/08/2008 1:34:25 PM

User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

Job Number: 41690

Part Number: D412742013

Job Number:



Seq. #:

Machine Or Operation:

Description:

40.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D412

Location:______(

41.0

QC21

FINAL MSPECTION/W/O RELEASE




08/10/02/18

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



N 68,1002



Dart Aerospace	Ltd
----------------	-----

Dail Aci	Copacc										
W/O:		WORK ORDER CHANGES									
DATE	STEP	PROC	EDURE CHA	NGE	GE By Date			te Qty Approval Chief Eng / Prod Mgr			
			•								
Part No	:	PAŖ #:	Fault Cate	egory: N	CR: Yes	No DQ	.: А:	Date:			
;						osed: Date:					
NCR:				ER NON-CONFORMANO							
	STEP Description of N	Description of NC	Corrective Action Section B			Verification		Approval	Approval		
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector		
		,									
							· · · · · · · · · · · · · · · · · · ·				
		\ \									
Ė											
					1						

Qty:

: FLOAT SKID ASSEMBLY

: D412742043

: 10/09/2008

: D3391

: N/A

: G

Date:

Friday, 29/08/2008 1:34:39 PM

User:

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

: 41690A : 10756

P.O. Number

This Issue

: 29/08/2008

: NC

Prsht Rev. First Issue

Previous Run Written By

: 41689A

: 29/08/2008 : SKIDTUBES Type

S.O. No. :

Checked & Approved By

Comment

: Est Rev A 05.10.13

Est Rev B 06.02.13 Est Rev:C 07-05-28 As per Rev F

Est Rev:D 07-12-04 ECN 1072

by:JLM

 \mathcal{C}_{i} New Issue

KJ/JLM EC ECN 773 dwg @ rev.D

JLM

DD verified

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

If D412-742-043 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-742-043 CHG003

2.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391

LPS-3 ~107912

2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment, using 7/16" "T" Pins.

Sikaflex-241/-29/1 ____/0880 / A/R

Expiry date:

3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon".

Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex.

LPS Procyon W/04251 A/R Sikaflex-241/-291, MO880/ A/R

Expiry date:

4-Remove "T" pins once sikaflex is dry.

5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser.

Each

1 Um:

N/O:		WORK ORDER O	WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
							3				
							July France				
Part No): 	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _					
	Re	solution: Disposition:	QA: N/C (closed:	·	Date: _					

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector		
÷										
			1							
					•					

Date: Friday, 29/08/2008 1:34:39 PM User: Julie Lecocq **Process Sheet Drawing Name: FLOAT SKID ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 41690A Job Number: **Description:** Seq. #: **Machine Or Operation:** Mid Tube Assembly 3.0 D3391023 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: pick: Part Number Description Qty D3391-023 Mid Tube Assembly D3391025 Aft Tube Assembly 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: pick: Qty Part Number Description D3391-025 Aft Tube Assembly D35641 Wearshoe Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARSHOES 409 D35661 Gasket 6.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) **GASKET** Batch: D35643 Wearshoe 7.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **WEARSHOE** D35645 Wearshoe 8.0 Comment: Qty.: **WEARSHOE**

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							· · · · · · · · · · · · · · · · · · ·			
			,							
Part No	•	PAR #:	Fault Cat	egory:	NCF	R: Yes I	No DQ/	A :	_ Date: _	
					QA: N/C Closed: Date:					
NCR:		1	WORK ORE	DER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC		·	ction B		Verific	ation	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
ļ										
					·					ļ
				•					}	

Friday, 29/08/2008 1:34:39 PM Date: User: Julie Lecocq **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 41690A Job Number: Description: Seq. #: Machine Or Operation: Gasket D35665 9.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: **GASKET** BOLT AN3C4A 10.0 . . Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) **BOLT** Batch AN3C6A BOLT 11.0 12.0000 Each(s) Comment: Qty.: 12.0000 Each(s)/Unit Total: **BOLT** Batch BOLT AN3C7A 12.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) **BOLT** Batch AN960C10L washer 13.0 44.0000 Each(s)/Unit Total: 44.0000 Each(s) Comment: Qty.: 0 + L 08/08/25 washer Batch INSPECT WORK TO CURRENT STEP 14.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 15.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 Location:_ 41690 S PPP Rev:

Dart Aerospace	Ltd
----------------	-----

	•									
W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	_ NCR	: Yes 1	lo DQ	A :	_ Date: _	
	R	esolution:	Dispositio	n:	_ QA:	N/C Clo	sed:		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORM	ANCE	(NCR))			
DATE	STEP	Description of NC	Corrective Action Section B		ion B	V _€		cation	Approval	Approval
DAIE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
					į					
						····				j
										t: 1
ļ t										

Date:

Friday, 29/08/2008 1:34:39 PM

User:

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKID ASSEMBLY

Job Number: 41690A

Seq. #:

Job Number:

Machine Or Operation:

Description:

Part Number: D412742043

16.0



FINAL INSPECTION/W/O RELEASE



08/10/02 4

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



W 8.10.02

Dart	Aeros	pace	Ltd
-------------	--------------	------	-----

W/O:		WORK ORDER CHANGES							
DATE STEP		PROCEDURE CHANGE	Ву	By Date		Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				· · · · · · · · · · · · · · · · · · ·					

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	•	Date:

NCR:	į	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C				
						i				

